

Technical Notice:

TMS no longer ships the 800F M series cables attached to the 800F TMS78 power supply and TMS23 hose control relay boards.

Please refer to the graphic below as a guide to correctly connect the 800F M cable to the IC box components.

